

Part-1
Performa For The Safety School Building
(To be filled by the Head of School/Institute)

1. Name of School : **Guru Nanak International Public School**
2. Location : **I-Block, Bhai Randhir Singh Nagar,**
Ludhiana
3. Plot Area : **10648 sq.yds.**
4. Plinth Area : **52904 sq.ft**
5. Number of Storey : **Two**
6. Year of Construction of building : **1987 to 2010**
7. Supervision of qualified Engineer,
The following details may be given :
- a) Name of the Engineer : **Contractor Sh.Jagdish Chand**
- b) Address : **V.P.Phullanwal, Near Monika Gas Agency,**
Ludhiana.
- c) Set of Structure Drawing used : **Latest - attached**
in the construction if available
- d) Name of the Architect : **M/s Bedi & Association**
8. (Whether the building has been constructed for the purpose of :
- a) School (Yes/No)
- b) Residential purpose and (Yes/No)
converted for use as a school
9. Materials used for Roof :
- a) R.C.C slabs (Yes/No)
- b) R.S.Joists and Battens (Yes/No)
- c) Wooden joists and Battens (Yes/No)
10. Materials used for walls :
- a) Mud Mortar (Yes/No)
- b) Cement Mortar (Yes/No)
- c) Plaster i) Lime Mortar (Yes/No)
- ii) Cement Mortar (Yes/No)
10. Flooring :
- a) Conglomerate (Yes/No)
- b) Terrazoo (Yes/No)
- c) Brick Paving (Yes/No)
11. Details Drawing indicating dimensions of the : Attached
rooms along with size and location of doors
and windows.

Kandhmi

Principal

G.N.I. Public School
I-Block, BRS Nagar, Ludhiana.

Part-II


(To be filled by S.D.E. of P.W.D. B & R Department)


I have visited the above mentioned school on 10/8/2022 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations or caves of roof etc. immediately inspection of the undersigned by arranged to check the stability and safety of the building.

This building can be safety occupied for normal use up to 31/3/2023
(indicate year up to which it can be used).


(Er. Taranjit Singh Arora)
Sub Divisional Engineer
Provincial Sub Division No.3,
P.W.D. B&R, Br. Ludhiana.


10/8/2022